# Oil Field Environmental Incident Summary

**Responsible Party:** SLAWSON EXPLORATION COMPANY, INC. **Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

Well Name: LUNKER FEDERAL 2-33-4H

Field Name: VAN HOOK Well File #: 23105

Date Incident: 12/23/2014 Time Incident: 06:05 Facility ID Number:

County: MOUNTRAIL Twp: 152 Rng: 91 Sec: 33 Qtr: NW NW

Location Description:

Submitted By: Ray Gorka Received By:

Contact Person: Ray Gorka

**1675 BROADWAY STE 1600** 

DENVER, CO 80202

General Land Use: Cultivated Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 3050 Feet **Distance Nearest Water Well:** 3050 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	1	Barrels	1	Barrels	1	barrels	
Brine	20	Barrels	19.5	Barrels	20	barrels	

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 4/18/2016 Clean Up Concluded: 12/24/2014

Risk Evaluation:

none....

Areal Extent:

.....

## Potential Environmental Impacts:

non	e	
HUL	<b>C</b>	

### Action Taken or Planned:

Reprimand the company, K & S and his supervisor and the driver and remind all drivers to close valves.

Wastes Disposal Location: Licensed company disposal well nearby.

Agencies Involved:

#### **Updates**

Date: 12/23/2014 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA